CM01 March 8, 1999

ECS Configuration C	Change Request				Page 1 of		Page(	
1. Originator	2. Log,Date: 3. CCR						6. Rm #:	7. Org.
Eric Obligacion	10/13/99	199-1	016	_	(301)614-5	114	C101R	EDS
8. Title of Change: Relocation	on of DIPHW and g0icg0			<u> </u>			•	
9. Originator Signature/Date 10. Class 11. Type: 12. Need Date: 09/16/99								
9. Originator Signature/Date			ZZ ZZ	CCR				
13. Office Manager Signature/Date / 9/16/89			14. Cate	gory of C	hange: 15. Priority: (If "Emergency"			
Lean Valle Dung Vo			Initial Baseline		fill in Block 28). Emergency			
16. Documentation/Drawing	17. Schedu							
GDAAC Floor Plan	ga mipaoteu.		inpact:		10. 0.(0) A			
GDAAC Cable Plan (Location change only) High								
19. Release Affected:		20. Date due to Cust			Impl. Date:	22. Estimated Cost:		
		09/16/99			16/99 None		· · · · · · · · · · · · · · · · · · ·	
23. Source Reference:   NCR (attach)  Action Item Tech Ref.  GSFC Other:								
24. Description of Change	: (use additional Shee	ts if necessar	y)		for the test			DAAC
The current location of the distribution segment (DIPHW) has an operational requirement for visibility and maintenance. GDAAC management realized that W30A is completely isolated from the operations console area. The equipment mentioned needed to be								
situated as close as possible to C101C were production could be accessed conveniently and supervised.								
25. Proposed Solution: (use additional sheets if necessary)								
Relocate DIPHW and g0icg03 from W30A to C101.								
26 Alternate Solution: Inc	se additional cheets if	necessary)						
26. Alternate Solution: (use additional sheets if necessary) The operation requires visibility and maintenance supervision, this isolated location is not acceptable.								
	•							
					<del> </del>			
27. Consequences if Change(s) are not approved: (use additional sheets if necessary)  Purchase additional equipment to comply with operation necessities.								
Purchase additional equipme	ent to comply with obeta	gon necesside:	<b>5</b> .					
							····	
28. Justification for Emerg	ency (If Block 15 is "E	mergency"):	D 50- CD 4 4					
This is a DAAC operation re-	quirement and must be d	completed ASA	r per GDAA	io manag	jement.			
29. Site(s) Affected:	DF Mini-DAAC	VATC DED	C ⊠GS	SFC L	aRC NSI	OC [	SMC AK	K □JPL
	OC DIDG Test Cell							
30. Board Comments:				31. Work Assigned To:			:	
32. EDF/REL2 CCB Chair	(Sign/Date):	33. Disposi	tion: App	proved	34.	(TBI	D)	
	· -	A/C	Disap	proved	1			
		Fwd/EC		ESDIS		C14 12	nagade Cla	eure:
35. M&O CCB Chair (Sign		36. Disposi	tion: App	roved) <del>prov</del> ed	37.	CIVI M	anager's Clo	ouit.
W But	290d9	Fwd/EC		Broved ESDIS				
38. ECS CCB Chair (Sign/		39. Disposi		roved	40.	CCR	Closed Date	:
			A/C					
CM01 March 8 1999			Disa	pproved		F	CS/EDF/REL	2 CCB
CAMO EMARCA & 1999						_	~~~~	